

Reference Sheet for Summit HF X-ray Generators

Annotated & reformatted by Roger Frueh, Tech Support, Aug 2007

All Models 30kW & 20kHz including: Synergy HF, Spectra 30HF, AMRAD 300HF, NHD 300

X-ray Generator		Power Module	Controller Software	Console Assembly	Console Software
Title	System Model				
300mA SYNERGY 2PT	L300-01 & L300-02	L177-01 & L177-02	L142-01	L160	L044-01 2 point
300mA OEM 2PT	L500*	L177-01 & L177-02	L142-02	L460	L044-02 2-point
300mA VET SELECT 2PT	00210-000	L741-00	L142-03	L843	L044-03
300mA MED APR	L550-01 through L550-08, & -10, -11, -22, -23	L177-01 and L177-02	L142-04	L501-01 or L501-03	L519-01 APR
300mA VET APR (Specialist)	L550-09	L177-01	L142-04	L501-02	L519-02
300mA VET SELECT APR	00210-002	L741-02	L142-04	01371-000	L519-03
300mA CHIRO APR	L550-12 through L550-19, & -24, -25	L177-01 and L177-02	L142-04	L501-05 or L501-06	L519-05
500mA VET SELECT 2PT	00210-001	L741-01	L142-05	L843	L044-03
500mA CHIRO APR	L550-20 & L550-21	L177-03 & L177-04	L142-06	L501-04	L519-04 APR
500mA SYNERGY 2PT	L300-03 & L300-04	L177-03 & L177-04	L142-07	L160	L044-01 2 point
500mA VET SELECT APR	00210-003	L741-03	L142-08	01371-001	L519-06
500mA VET APR (Specialist)	L550-26	L177-03	L142-06	L501-09	L519-07
500mA MED APR	L550-27 & L550-28	L177-03 & L177-04	L142-09	L501-10	L519-08 APR
300mA APR VET DXR	02968-001	02953-001	L142-04	01371-002	L519-09
500mA APR VET DXR	02968-002	02953-002	L142-06	01371-003	L519-10

Software

DEVICE

Part No. Current Vers. & release date:

HISTORICAL Vers. & Release Dates:

Console 2point	L044 Ver 1.03	08/02/ 2001	V 1.02, -- ? --
P.Mod Controller	L142 Ver 1.26	06/17/ 2007	V 1.25, 17mar06 <O> V1.24, 10feb06 <O> V1.23, 16jun05
Console APR	L519 Ver 1.14	06/20/ 2007	V 1.13, 01sep06 <O> V 1.11, 21jul05 <O> V 1.10, 28apr05
OBSO	:		
L050 Controller	02503 Ver 1.01	05/16/2005 >>	The original System controller, MFG Jan 2000 thru June 2002